

## **Dear Customer:**

This Turbocharger has been supplied complete for your application. A Core charge has been applied to your invoice and a full refund will be given if the returned unit meets the "acceptance criteria" listed below. This determination is solely that of GCG Turbochargers Australia Pty Ltd.

## **Core Acceptance Criteria**

- 1. The old turbocharger must be returned within 30 days from invoice date, <u>freight pre-paid</u>.

  <u>You must include/return the Credit Claim attached to the invoice as the linking document</u>
  for your credit to be accepted and paid.
- 2. The old turbocharger must be returned complete, with no loose clamps or housings.
- 3. The old turbocharger must be returned "as removed from the engine" and not disassembled in any way and include the waste gate actuator or VNT controller (where applicable).
- 4. The old turbocharger must be of the same model/part number as the one supplied.
- 5. The old turbocharger has no "non-operational damage due to one, or any of the conditions listed below:-
  - (a) Cracked/broken flanges or housings.
  - (b) External Damage to turbine and compressor housings of any kind.
- 6. The old turbocharger must not have been in the following:-
  - (a) A vehicle or engine fire
  - (b) Submerged in water or weathered by leaving out in the elements
  - (c) A car accident causing impact damage to the turbocharger
  - It is important to understand the reason the original Turbocharger failed and to rectify the problem prior to installing the new unit.
- It is important that you follow our instruction when re-fitting this turbocharger.
- Warranty is per our standard Warranty Policy.

PLEASE ENSURE YOU REMOVE ALL OIL AND WATER FITTINGS FROM THE ORIGINAL UNIT AS THESE WILL <u>NOT</u> BE SUPPLIED WITH A SERVICE EXCHANGE UNIT.

Dated 1st March 2017.